



Doing Business with Boeing
Approved Process Sources D1-4426

Doing Business with Boeing Home
[Close](#)

Approved Process Sources D1-4426

Document D1-4426 - Processes for BE10028864

[Boeing Approved Process Sources - Home](#)

[Nadcap Accreditation](#)

[Notes & Exceptions](#)

[Revision Summary](#)

Detail Information for Processor Code number: BE10028864

[User Instructions &](#)

[Background Cases](#)

[Approved Processors](#)

[Geographic APL](#)

[Process Code Listin](#)

[Classification Today's Listin](#)

Address: 18100 S WILMINGTON AVE,
City/town: RANCHO DOMINGUEZ
Province/state: CA 90220
Country: UNITED STATES
Area: CA
Contact Name: Kristina Plaza

[400A](#) [NDT](#)

[402](#) [NDT](#)

[403](#) [NDT](#)

Phone: [NDT](#) 310-632-8500 21253

Fax: [310](#) [NDT](#)

Process ***Nadcap** **Limitation** **Doc Notes** **Nomenclature** **Classification**

stainless steels.

Also approved to pre-penetrant touch

Liquid Penetrant

410A NDT

411 NDT

412 NDT

420A NDT

421 NDT

430 NDT

430A NDT

430B NDT

431 NDT

431A NDT

431B NDT

432 NDT

434 NDT

436A NDT

436B NDT

436C NDT

436E NDT

437 NDT

magnesium, and stainless steels.

Also approved to pre-penetrant touch

None

aluminum, titanium, magnesium, and stainless steels

Penetrant Inspection

STM-E-1417

Also approved to pre-penetrant touch

None

aluminum, titanium, magnesium, and stainless steels.

Penetrant Inspection

MIL-STD-866

Standard Practice for

| | | | | | | | |
|----------------------|---------------------|--------------------|--|--|--|--|---|
| 437A | NDT | | | | | | |
| 437C | NDT | | | | | | 2 |
| 510 | CP | | | | | | |
| 809 | CP | | | | | | |
| 848A | NDT | A3 | | | | | |

[848B](#) [NDT](#) [A3](#)

[850A](#) [NDT](#) [A3](#)

[851A](#) [NDT](#) [A3](#)

None None

Ultrasonic Inspection of
Rounds and Curved
Shapes STM-E-
375

None Method II

Cleaning - Descaling of
Titanium Method II PIG-5762

[L410](#) [NDT](#)

[L421](#) [NDT](#)

[L424](#) [NDT](#)

None

Process Solution
Control

Chem.
Testing

[L428](#) [NDT](#)

[L430B](#) [NDT](#)

[M400](#) [NDT](#)

[M410A](#) [NDT](#)

[M424](#) [NDT](#)

[S400](#) [NDT](#)

[S400](#) [NDT](#)

| | | | | | |
|-----------------------|---------------------|------|------------------------------------|---|---------|
| S410A | NDT | None | Iso | Penetrant Inspection - | PS21202 |
| S410B | NDT | | P3 | | |
| S410C | NDT | | | Penetrant Inspection - Be llium | PS21202 |
| S410D | NDT | None | Iso approved to pre-penetrant tch. | Penetrant Inspection - Cobalt - Nickel | PS21202 |
| S410E | NDT | None | Iso approved to pre-penetrant tch. | Penetrant Inspection - Copper | S21202 |
| S410H | NDT | | | | |
| S410J | NDT | None | Iso approved or pre- | Penetrant Inspection Maanesium | PS21202 |
| S421 | NDT | | | | |
| S430 | NDT | None | tch. | Penetrant Inspection Stainless Steels | PS21202 |
| S430G | NDT | | | | |

[Copyright](#)

[Security Agreement](#)